

**Project:** Cheltenham Art Gallery and Museum.

**Client:** ISG Pearce Ltd

**Brief:** Maylarch Environmental acted as a Sub Contractor to carry asbestos removal work to all areas within the scope boundary and demolition in accordance with demolitions drawings.



This project needed careful planning due to the tight confines of the site as the buildings due to be demolished adjoined two grade one listed buildings with basements on either side and within Cheltenham town centre.

The buildings were carefully separated from the building to remain with scaffold protection to roads. Demolition consisted as a mix of hand demolition and machine due to the nature of the site. Demolition works to underside of slab were done in conjunction with an archaeological field survey.

All hardcore was crushed on site using a crusher bucket, which saved the contractor importing material to fill old basements and level site. The project was done to agreed program times

Maylarch Environmental Limited  
[www.maylarch.co.uk](http://www.maylarch.co.uk)

Oakwood, Oakfield Industrial Estate  
Eynsham, Oxfordshire OX29 4TH  
T: 01865 883829 F: 01865 881376  
E: [enquiries@maylarch.co.uk](mailto:enquiries@maylarch.co.uk)